

DISPOSAL PICK UP.

State of California--Health and Welfare Agency

04/08/87

Don
Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address Silicon General 11651 Monarch, Garden Grove, CA 92641		CA ID 101 77100 12120 13			A. State Manifest Document Number 86544211
4. Generator's Phone (714) 898-8121					B. State Generator's ID CAD0077012203
5. Transporter 1 Company Name Omega Recovery Services		CA ID 04 2 24 5 001			C. State Transporter's ID 865425
6. Transporter 2 Company Name					D. Transporter's Phone 213/698-0991
7. Designated Facility Name and Site Address Omega Recovery Services 12504 E. Whittier Blvd. Whittier, CA 90602					E. State Facility's ID CAD042245001
8. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)					F. Facility's Phone 213/698-0991
9. Waste Corrosive Liquid NOS UN 1760 Corrosive (Micro strip)					
10. Containers					
11. Additional Descriptions for Materials Listed Above					
12. Special Handling Instructions and Additional Information Advise Ali Ashmir of disposal costs and state get P.O. Number at that time.					
13. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. Unless I am a small quantity generator who has been exempted by statute or regulation from the duty to make a waste minimization certification under Section 3002(b) of RCRA, I also certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I minimize the present and future threat to human health and the environment.					
14. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name: Donald Tryon Signature: Donald Tryon Month Day Year: 10/4/17/87					
15. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name: Isaac Woods Jr Signature: Isaac Woods Jr Month Day Year: 04/11/87					
16. Discrepancy Indication Space					
17. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19. Printed/Typed Name: FRANK FORD Signature: Frank Ford Month Day Year: 10/4/17/87					

DHS 8022 A (11/85)
(EPA 8700-22)White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS -
To: P.O. Box 3000, Sacramento CA 95812

8705 19 0023 00:10